




Crown Automotive Sales Co., Inc.

Mirror Adjustment Notes



Please note:

There are two Phillips Head screws under the mirror head. These screws are purposely not tightened at the factory. Adjust the mirror to the desired position and then tighten the screws $\frac{1}{4}$ turn past hand tight. Failure to tighten these screws will cause the mirror to rattle while driving. Over-tightening the screws will result in damage to the mirror.

While every attempt is made to ensure that the information contained in these instructions is correct, no liability can be accepted by the authors for loss, damage, or injury caused by any errors in, or omissions from the information given. All service should be performed by qualified mechanics. Crown Automotive Sales Co., Inc. cannot be held responsible for any mechanical work performed. Standard and accepted safety precautions should be used in every procedure.