



RT Off-Road

Revision Notice

Replaces Part No: CVSYE231

The nipple-style grease fittings that are installed in P/N: CVSYE231 may come in contact with the propeller shaft body or a transfer case output yoke in some applications. Enclosed are 3 needle-style grease fittings. Install them in place of the nipple-style grease fittings in any tight areas where additional space is needed.

While every attempt is made to ensure that the information contained in these instructions are correct, no liability can be accepted by the authors for loss, damage or injury caused by any errors in, or omissions from the information given. All service should be performed by qualified mechanics. Crown Automotive Sales Co., Inc. cannot be held responsible for any mechanical work performed. Standard and accepted safety precautions and equipment should be used in every procedure.



RT Off-Road

Revision Notice

Replaces Part No: CVSYE231

The nipple-style grease fittings that are installed in P/N: CVSYE231 may come in contact with the propeller shaft body or a transfer case output yoke in some applications. Enclosed are 3 needle-style grease fittings. Install them in place of the nipple-style grease fittings in any tight areas where additional space is needed.

While every attempt is made to ensure that the information contained in these instructions are correct, no liability can be accepted by the authors for loss, damage or injury caused by any errors in, or omissions from the information given. All service should be performed by qualified mechanics. Crown Automotive Sales Co., Inc. cannot be held responsible for any mechanical work performed. Standard and accepted safety precautions and equipment should be used in every procedure.



RT Off-Road

Revision Notice

Replaces Part No: CVSYE231

The nipple-style grease fittings that are installed in P/N: CVSYE231 may come in contact with the propeller shaft body or a transfer case output yoke in some applications. Enclosed are 3 needle-style grease fittings. Install them in place of the nipple-style grease fittings in any tight areas where additional space is needed.

While every attempt is made to ensure that the information contained in these instructions are correct, no liability can be accepted by the authors for loss, damage or injury caused by any errors in, or omissions from the information given. All service should be performed by qualified mechanics. Crown Automotive Sales Co., Inc. cannot be held responsible for any mechanical work performed. Standard and accepted safety precautions and equipment should be used in every procedure.