

## Crown Automotive Sales Co., Inc. 4666153AC Installation Tips

The lower oil pan to upper oil pan mating surface is already equipped with RTV sealant and is cured to prevent leaks. However, the hardware needs to be torqued to spec prior to installation.

## Bolt Location

Lower Oil Pan to Upper Oil Pan Upper Oil Pan to Engine Block Oil Drain Plug

## **Torque Spec**

105 in. lbs (8.75 ft. lbs.) 105 in. lbs (8.75 ft. lbs.) 20 ft. lbs.

## Ensure proper torque of parts. Improper torque may cause premature wear or failure.

While every attempt is made to ensure that the information contained in these instructions is correct, no liability can be accepted by the authors for loss, damage, or injury caused by any errors in, or omissions from the information given. All service should be performed by qualified mechanics. Crown Automotive Sales Co.,Inc. cannot be held responsible for any mechanical work performed. Standard and accepted safety precautions should be used in every procedure.